	The state of the s			2 1 27				an a same in a	erri -
ŧ	Approved For Rele						700150031	-8 [4]	STATE OF THE STATE
ANDER	2012Z 27 OCT 63	SE	: C R	E		12	«Манента при при настрой п	$-\left \frac{5}{6}\right $	MANNES (no select subsections is established than see the energian piece this editor , a ship (ANCO).
		TO STATE COME BY THE SERVICE		ni et inik k	ark in suit of our democracy in sate extension in the	5. T. L.	Control of	5 - 5	CONTROL OF THE PROPERTY OF T
- in - in Adding the areas	deligned by distributed and approximately related to the content of the content o	magnitise entiremente i to a consiste all a consiste and a consist	Line	. Trans	iki sa nasawa sa sahisim sa ka samasika basa na dina sa ka sa sajarah mataya ya siyayaya Mir	A Company			
ïO	<sub>k</sub> DIRECTOR					The section of the se			
5X1A <sub>2208</sub>						- 000			- A B
						Property Control of State			
acti	on: OPS 1-7						PRIM		
						4.4	IMA		The second control of
info									
	TOR Ø1Ø5Z 28 OCT 63							IN	97607
d manufacturer inc	ng maga kapay kamangga.	magazan aras gaz yerancago a segupa			and the second control of the second control	m 1 3900 3 mol		The state of the s	
5X1A	PRIORITY	ki FO				a narande	CITE		ø 1 ø 2 2 5 X 1
		4.41 <b>8. 16.87</b>					40E S E2		
	·								
5X1A									

A. G-3235

B. LMOD

C. VERY SMALL BLACK HAIRLINE EMULSION ABRASIONS ON 9R 13/16 INCH FROM TITLED EDGE AND DOWN CENTER OF FRAME PLUS SEVERAL OTHER INTERMITTENT ABRASIONS OF SAME TYPE FROM FRAME NO 2130 TO END OF FILM. INTERMITTENT ABRASIONS MOSTLY IN AND ALONG TITLED EDGE. THESE BELIEVED TO BE CAUSED BY CAMERA MAGAZINE SINCE BACK-UP TRAILER FROM SAME PROCESSOR SHOWS NO EVIDENCE OF MACHINE ABRASIONS. 9L ROLL SHOWS NO DEFECTS OF SIMILAR TYPE. ALSO SMALL HAIRLINE MARK ON 9R LOCATED NEAR EDGE OF DATA CHAMBER. APPEARS TO BE CAUSED BY SMALL PIECE OF LINT IN DATA CHAMBER.

END OF MESSAGE

SECRET

CRISED 3 Excluded from actuments descripting and destassification